



"pulling the fuel lines through and disconnecting the engine bay ancillaries was next on the list, followed by a comprehensive search for rogue earth straps and cable lies. This may sound like an obvious and mundane job, but the heated rear screen was actually earthed via an eleven foot piece of wire direct to the coil – yes really!"

